



TANGENT CROWN (TC) CANNOT BE PLACED AT THE BOTTOM OF A VERTICAL CURVE. LOCATION OF RUNOFF SHALL BE ADJUSTED AS DIRECTED BY THE PROJECT ENGINEER.